






TALON LOK[®] 1000 NAIL FLANGE INTEGRAL PANEL / TLNF 1000



Note:

-Oil Canning is not a cause for rejection. Using Stiffening Ribs or Striations can help reduce oil canning but will not completely eliminate it



**AMERICAN ARCHITECTURAL
METAL MANUFACTURERS, INC.
EAGLE METAL ROOFING
SYSTEMS TALON LOK[®] PANEL
SPECIFICATIONS**

**TALON LOK[®] 1000 NAIL FLANGE
INTEGRAL PANEL / TLNF 1500**