






# TALON SEAM 1000 / TS 1000 1" HIGH DOUBLE LOCK STANDING SEAM




BEFORE SEAM:



SINGLE LOCK:



DOUBLE LOCK:



Note:

-Oil Canning is not a cause for rejection. Using Stiffening Ribs or Striations can help reduce oil canning but will not completely eliminate it



AMERICAN ARCHITECTURAL  
METAL MANUFACTURERS, INC.  
EAGLE METAL ROOFING  
SYSTEMS TALON LOK® PANEL  
SPECIFICATIONS

TS 1000 1" HIGH DOUBLE LOCK  
PANEL