



# TALON LOK® 1500 1 1/2" HIGH NAIL FLANGE INTEGRAL PANEL TLNF 1500



**Note:**

-Oil Canning is not a cause for rejection. Using Stiffening Ribs or Striations can help reduce oil canning but will not completely eliminate it



AMERICAN ARCHITECTURAL METAL MANUFACTURERS, INC.  
 EAGLE METAL ROOFING SYSTEMS TALON LOK® PANEL SPECIFICATIONS

TALON LOK® 1000 NAIL FLANGE INTEGRAL PANEL / TLNF 1500