





TALON LOK® 1000 1" HIGH INTEGRAL PANEL WITH CLIP / TLC 1000



Note:

-Oil Canning is not a cause for rejection. Using Stiffening Ribs or Striations can help reduce oil canning but will not completely eliminate it



AMERICAN ARCHITECTURAL METAL MANUFACTURERS, INC.
EAGLE METAL ROOFING SYSTEMS TALON LOK® PANEL SPECIFICATIONS

TALON LOK® TLC 1000 1" HIGH INTEGRAL PANEL